

- Legend**
- | | |
|--|---|
| Preliminary Site Plan | Highway Realignment |
| ★ Borrow Source; T= Till & S= Sand | --- New Highway 11 Alignment |
| ▲ Explosive Plant | Existing Features* |
| ▲ Fresh Water Pumping Station | ▲ Consolidated Mosher Long Lac Historic Shaft |
| ⊠ Goldfield Dam | — Highway |
| ⓘ Potential Information Center | — Major Road |
| ⓪ Potential OPP Station | — Local Road |
| ⊙ Outfall Locations | — Existing Power Line |
| ▲ Proposed MTO Yard | — Watercourse |
| ⊠ Temporary Work Camp | ⊠ Historic Tailings Area |
| ⊙ Water Course Crossing | ⊙ Mosher Pit |
| ⊠ Future Substation 115kV | ⊠ Provincial Park |
| ⊙ New Longlac TS 115kV | ⊠ Wetland, Unevaluated |
| — Access Road | ⊠ Waterbody |
| --- Construction Access Road | |
| → Diversion Channel | |
| → Fresh Water Pipeline | |
| → Haul Road | |
| — New Power Line 115kV | |
| — Power Line Realignment 44kV | |
| --- Tailings Pipeline and Overhead Powerline | |
| ⊙ Inundated Area | |
| ⊙ In Pit Dumping- Waste Rock | |
| ⊙ Open Pit- Full Extent | |
| ⊙ Ore Stockpile | |
| ⊙ Process Plant Area | |
| ⊙ Potential Collection Ponds | |
| ⊙ Tailings Management Facility | |
| ⊙ Waste Rock Storage Area | |


DRAFT

- Notes**
1. Coordinate System: NAD 1983 UTM Zone 16N
 2. Base features produced under license with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2013.
- *. Existing Features have been removed in the PDA and do not reflect current conditions.
- March 2015
160960946

Client/Project
Premier Gold Mines Hardrock Inc
Hardrock Project

Figure No.
4-1

Title
Site Plan



W:\active\60960865\drawing\MXD\EA\APC Reports\Project_Description\Chapter\160960946_PDC_Fig_4_1_SitePlan_20150330.mxd
 Revised: 2015-03-30 By: dharvey

DRAFT